TECHNOLOGY EDUCATION

NAME		

GENERAL SAFETY RULES

- 1. Report all injuries to the teacher, no matter how small they may be.
- 2 Safety glasses, eye protection must be worn when working on and around machines.
- 3. Stay away from any person operating a machine. Never talk to an operator or approach them from behind.
- 4. Only one person operating or standing near a machine.
- 5. Always get the instructors permission before using a machine, no matter how many times you have used them before.
- 6. Loose clothing and jewelry being worn around machinery is dangerous. Be sure loose sleeves and clothing are secured.
- 7. Never make adjustments on machines unless you are instructed to do so. Disconnect power before making adjustments.
- 8. Any tools that are dull or broken should be reported to the teacher for repair or replacement.
- 9. Towels and rags with toxic oil, thinner and/or finish must be put in the metal safety container. No wood scraps, dust or paper in container.
- 10. Anyone miss using or fooing with machines will not be allowed in the machine area.
- 11. There is to be no running or loud talking at any time.
- 12. Never throw "anything" in the laboratory working area.
- 13. Fooling around is "absolutely forbidden" safety is everyone's job.
- 14. Sandals and open toe shoes are dangerous.
- 15. Long hair must be secured before working with and around machines.
- 16. Wear gloves when working with hot, sharp and toxic materials.
- 17 Use all resources in a safe and environmental way.